

DCA-169

DCA-170

Racine Railroad Products

1955 Norwood Court Mount Pleasant WI, 53403 (262) 637-9681 www.racinerailroad.com

Service Bulletin Maintenance of Way Equipment

					-	1	r	
Date: 11.14.2022					RRP Ser	vice Bu	ılletin No:	RRP SB384
Title: Ac	ljusting tl	he PE4	045U152740	Deere	Cooler to	prevent	radiator da	mage.
Rating:								
[ALERT				INFORMATION			
	X (Potential Problem)				(Action Is Optional)			
(i oteritian robiem)					<u> </u>	(Action	is Optional)	
[DIRECTIVE					PRODU	CT IMPRO	VEMENT
	(Action Is Required)					(Enhand	ce Product)	
L	(/	ACTION IS	s ixequireu)		\ 	Lillali	be i foduct)	
Duaduat	Cariaa 9	Comini	No. OEN 4					
Product	Series &	k Seriai	No: GEN 4	DEEKE	Engines.			
APTI-054	931588	UPRR	RLPI-2102	DEERE	PE4045U1	.37130		
APTI-055	931588	UPRR	RLPI-2103	DEERE	PE4045U1	.09779		
ATPI-056	931588	UPRR	RLPI-2104	DEERE	PE4045U1	.06978		
ATPI-057	931588	UPRR	RLPI-2105	DEERE	PE4045U1	.37437		
ATPI-058	931588	UPRR	RLPI-2106	DEERE	PE4045U1	.39124		
ATPI-059	931588	UPRR	RLPI-2107	DEERE	PE4045U1	.39125		
ATPI-060	931588	UPRR	RLPI-2108	DEERE	PE4045U1	.39123		
ATPI-061	931581	UPRR	RLPI-2201	DEERE	PE4045U1	.39123		
D 4 4 262	004500		1100 0101	55555	DE 40 45 TEO	00		
DAA-363	931583	UPRR	AASQ-2101	DEERE	PE4045TFC			
DAA-364	931583	UPRR	AASQ-2102	DEERE	PE4045TFC			
DAA-365	931583	UPRR	AASQ-2201	DEERE	PE4045U15	2/40		
DAS-297	931584	UPRR	AASP-2101	DEERE	PE4045U	137128		
DAS-298	931584	UPRR	AASP-2102	DEERE	PE4045U	108942		
DAS-299	931584	UPRR	AASP-2201	DEERE	PE4045-L	J152739		

931585 UPRR ECAM-2101 DEERE PE4045U137129

931585 | UPRR | ECAM-2102 | DEERE | PE4045U139106



Racine Railroad Products

1955 Norwood Court Mount Pleasant WI, 53403 (262) 637-9681 www.racinerailroad.com

Summary: The cooler may be mounted too close to the radiator and may cause damage to the radiator during machine operation.

Action: Remount the cooler on the outside of the bracket to give it more room and add washers in between if needed.

Completion / Resolution:

Continue with normal machine operation after remounting the cooler.

Issue


No space between the cooler and the radiator.

Bracket on the outside of the cooler.



Resolution

- 1. Remount the cooler bracket on the inside of the cooler frame.
 - This provides more room between the cooler and the radiator.
- 2. Add washers in between if needed.



Contact: If you have any questions or we can be of any service, please contact the Racine Railroad Products Service Department at (262)-637-9681 or fieldservice@racinerailroad.com.