

Service Bulletin

Maintenance of Way Equipment

Date: 2/10/2023**RRP Service Bulletin No:** RRP SB386**Title:** Correct a programing issue preventing John Deere equipped machines from regening.**Rating:****ALERT**

(Potential Problem)

**INFORMATION**

(Action Is Optional)

**DIRECTIVE**

(Action Is Required)

**PRODUCT IMPROVEMENT**

(Enhance Product)

Product Series: Advanced Tie Plate Inserter [ATPI], Dual Anchor Adjuster [DAA], Dual Anchor Spreader [DAS]**Serial No:**

APTI-032	933588	CP	7014-14
ATPI-035	933588	CP	5014--20
ATPI-036	933588	CP	5014.21
APTI-037	933588	CP	5014-22
ATPI-038	933588	CP	5014-23

APTI-053	931588	UPRR	RLPI-2101
APTI-054	931588	UPRR	RLPI-2102
APTI-055	931588	UPRR	RLPI-2103
ATPI-056	931588	UPRR	RLPI-2104
ATPI-057	931588	UPRR	RLPI-2105
ATPI-058	931588	UPRR	RLPI-2106
ATPI-059	931588	UPRR	RLPI-2107
ATPI-060	931588	UPRR	RLPI-2108
ATPI-061	931588	UPRR	RLPI-2201

DAA-355	931583	UPRR	AASQ-1901
DAA-356	931583	UPRR	AASQ-1902
DAA-357	931583	UPRR	AASQ-1903
DAA-358	931583	UPRR	AASQ-1904
DAA-359	933583	CP	8010-01

DAA-360	931583	UPRR	AASQ-2002
DAA-363	931583	UPRR	AASQ-2101
DAA-364	931583	UPRR	AASQ-2102
DAA-365	931583	UPRR	AASQ-2201

DAS-275	931584	UPRR	AASP-1901
DAS-276	931584	UPRR	AASP-1902
DAS-282	931584	UPRR	AASP-2001
DAS-297	931584	UPRR	AASP-2101

DAS-298	931584	UPRR	AASP-2102
DAS-299	931584	UPRR	AASP-2201
DAS-283	933584	CP	5013-18

Summary: A programming issue is preventing John Deere equipped machines from regening. This will eventually cause the engine to shut down until the issue is corrected.

Action:


Contact development@racinerailroad.com with the following information:

1. Machine Serial Number.
2. Machine Running Number.
3. Modem Serial Number.
4. Contact Information.
5. Work schedule for the next two weeks.

We will need to know if the gang is working days or nights and what time periods. This will be important for us to plan remote updates and eliminate as many unnecessary questions as possible.

The modem is located mounted on the back of the cab.

The modem serial numbers can be found on the modem data label.



Completion / Resolution: Continue with normal machine operation after program update.