

Service Bulletin

Maintenance of Way Equipment

Date: 04/238/2025**RRP Service Bulletin No:** RRP SB397**Title:** Replace Cummins Engine Placard**Rating:****ALERT**

(Potential Problem)

**INFORMATION**

(Action Is Optional)

**DIRECTIVE**

(Action Is Required)

**PRODUCT IMPROVEMENT**

(Enhance Product)

Product Series: AAM and AM3 Anchor Applicators**Serial No:**

AAM-018	931572	UPRR	AAA-2001
AAM-019	931572	UPRR	AAA-2002
AAM-020	931572	UPRR	AAA-2003
AAM-021	931572	UPRR	AAA-2004
AAM-023	931572	UPRR	AAA-2301
AAM-024	931572	UPRR	AAA-2302
AAM-025	931572	UPRR	AAA-2303

AM3-001	930589	UPRR	AAA-2407
AM3-002	931589	UPRR	AAA-2401
AM3-003	931589	UPRR	AAA-2402
AM3-004	931589	UPRR	AAA-2003
AM3-005	931589	UPRR	AAA-2404
AM3-006	931589	UPRR	AAA-2405
AM3-007	931589	UPRR	AAA-2406

Summary: The Cummins engine placard has the incorrect oil filter part number listed.**Action:** Order RRP Part # 478513 with the correct oil filter part number.**Completion / Resolution:** Continue with normal machine operation after replacing the correct engine placard.**Contact:** If you have any questions or we can be of any service, please contact the Racine Railroad Products Service Department at (262)-637-9681 or fieldservice@racinerailroad.com.