
Service Bulletin

Maintenance of Way Equipment

Date: 4/24/2025

RRP Service Bulletin No: RRP SB398

Title: OTM Reclaimer: The Functions Disable button may not work as intended. In the event of an issue, use the **Emergency Stop** button.

Rating:



ALERT

(Potential Problem)



INFORMATION

(Action Is Optional)



DIRECTIVE

(Action Is Required)



PRODUCT IMPROVEMENT

(Enhance Product)

Product Series: OTM Reclaimer

Serial No: 933587

Summary: A condition has been identified where if a short circuit occurs during *work mode* operation that causes the XC44 I/O Control Module to be unpowered.

The Functions Disable button may not work as intended. The service brake may not apply when Function Disabled button is pushed. *In the event of an issue, use the **Emergency Stop** button.*

Action: Use Emergency Stop button to stop the machine in the event of service brake not applying.

Contact: If you have any questions or we can be of any service, please contact the Racine Railroad Products Service Department at (262)-637-9681 or fieldservice@racinerailroad.com.