

NO.	QTY	DESCRIPTION	PART NO.		
1	REF	COVER, CABLE	318557		
2	REF	NUT, HEX ES: 8-32	491011		
3	REF	WASHER, FLT: #8	492036		
4	REF	SCR, HEX: 8-32 X .75	492037		

## INSTRUCTIONS:

OPEN COVER, POSITION WIRES TO CLEAR AREA FOR DRILLING.

- 1 POSITION COVER ONTO CONTROL BOX AS SHOWN.
- 2 TRANSFER HOLE LOCATIONS.

ΕN

- 3 CAREFULLY DRILL THROUGH WALL.
- 4 INSTALL COVER WITH SUPPLIED FASTENERS.
- 5 REMOVE CHIPS FROM INSIDE BOX.

		526011111011											
1	1 3020 NEW RELEASE									3-18	MSO		
DIMENSION TOLERANCES UNLESS OTHERWISE SPECIFIED													
	LINEA	.XX=±.03			.XXX=±.010								
	ANGULAR			X°=±1°			X.X°=±.5°						
SURFACE FINISH 125/ SMOOTH ALL SHARP EDGES OF THE S											OGES		
THIS PRINT AND ALL INFORMATION WITHIN BELONGS TO RACINE RAILROAD PRODUCTS													
R	ACI	NE I		ILR NE, W					)[	OUC	TS		
DESCRIPTION													
	INS	STRU	СТІ	ONS	ò,	W	IRE	С	Ο,	√ER			
МАТ	ERIAL			SEE	В	ОМ							
USE	NO C	7930	010				SCAI 1:4	-		E 3-27-	-18		
DRN	MSO	СНК		APP			B NO D150		- 1	SHEET 1 OF	1		
EXP	NO					DW	G NC		8(	002	72		

DESCRIPTION

DATE DRN