

# Service Bulletin

## Maintenance of Way Equipment

**Date:** 9.17.2021

**RRP Service Bulletin No:** RRP SB372

**Title:** Guide Roller Kit

**Rating:**



**ALERT**  
(Potential Problem)



**INFORMATION**  
(Action Is Optional)



**DIRECTIVE**  
(Action Is Required)



**PRODUCT IMPROVEMENT**  
(Enhance Product)

**Product Series:** Advanced Tie Plate Inserter [ATPI]

**Serial No:**

**UPRR**

ATPI-002-17	915574	UPRR	RLPI-1701
ATPI-003-17	915574	UPRR	RLPI-1702
ATPI-004-17	915574	UPRR	RLPI-1703
ATPI-005-17	915574	UPRR	RLPI-1704
ATPI-006-17	915574	UPRR	RLPI-1705
ATPI-007-17	915574	UPRR	RLPI-1706

ATPI-011	915574	UPRR	RLPI-1801
ATPI-012	915574	UPRR	RLPI-1802
ATPI-013	915574	UPRR	RLPI-1803

ATPI-023	931588	UPRR	RLPI-1901
ATPI-024	931588	UPRR	RLPI-1902
ATPI-025	931588	UPRR	RLPI-1903
ATPI-026	931588	UPRR	RLPI-1904
APTI-053	931588	UPRR	
APTI-054	931588	UPRR	

APTI-055	931588	UPRR	RLPI-2103
ATPI-056	931588	UPRR	RLPII-2104
ATPI-057	931588	UPRR	RLPI-2105
ATPI-058	931588	UPRR	RLPI-2106
ATPI-059	931588	UPRR	
ATPI-060	931588	UPRR	

**BNSF**

ATPI-014	932574	BNSF	X3800191
ATPI-015	932574	BNSF	X3800192
ATPI-016	932574	BNSF	X3800193
ATPI-017	932574	BNSF	X3800194
APTI-045	932587	BNSF	X3800196

APTI-046	932587	BNSF	X3800197
APTI-047	932587	BNSF	X3800198
APTI-048	932587	BNSF	X3800199
APTI-049	932587	BNSF	X3800200
APTI-050	932587	BNSF	X3800195

**CN**

ATPI-009	935574	CN	438-61
ATPI-010	935574	CN	438-62
ATPI-019	935588	CN-W	CN43865
ATPI-020	935588	CN-W	CN43866
ATPI-021	945588	CN-S	CN43863
ATPI-022	945588	CN-S	CN43864

ATPI-030	935588	CN-W	CN43867
ATPI-031	935588	CN-W	CN43868
APTI-042	935588	CN	CN43869
ATPI-043	935588	CN	CN43870
APTI-051	945588	CN-S	438-71
APTI-052	945588	CN-S	438-72

**CP**

ATPI-008	933574	CP	5014-19
ATPI-036	933588	CP	5014-21
APTI-037	933588	CP	5014-22

ATPI-038	933588	CP	5014-23
APTI-032	933588	CP	7014-14
ATPI-035	933588	CP	5014--20

**Relam**

ATPI-034	932587	RELAM
ATPI-041	932587	RELAM
APTI-044	932587	RELAM

**Summary:**

**Action:** Replace guide roller.

**Completion / Resolution:** Continue with normal machine operation after replacing the guide roller with the 793123 Kit.

If you have any questions or we can be of any service, please contact the Racine Railroad Products Service Department at (262)-637-9681 or [fieldservice@racinerailroad.com](mailto:fieldservice@racinerailroad.com).

## Guide Roller Kit / RRP# 793123

NO.	QTY	DESCRIPTION	PART NO.
1	4	PIN, COTTER: .19 X 1.5	400904
2	4	ROLLER	719470
3	1	INSTRUCTIONS, GUIDE ROLLER KIT	800360

1. Pull clevis pin and remove old roller (4 places).
2. Insert new roller and re-install existing clevis pin with new cotter pin (4 places).





