
Service Bulletin

Maintenance of Way Equipment

Date: 8/25/2022

RRP Service Bulletin No: RRP SB383

Title: Correct hex nut part number for 910196 UltraKut III power head

Rating:

ALERT
(Potential Problem)

INFORMATION
(Action Is Optional)

DIRECTIVE
(Action Is Required)

PRODUCT IMPROVEMENT
(Enhance Product)

Product Series: 910196 UltraKut III powerhead RRP# 718833

Summary: Wong part number for Item 16 on drawing 718833. Correct part hex flange nut M8-1.25 is RRP# 476627 (not 474473).

Action: Contact RRP Customer Service at to order replacement nuts [RRP# 476627] at no charge.

Completion / Resolution: Continue with normal machine operation after replacing with correct parts.