

NO.	QTY	DESCRIPTION	PART NO.
1	REF	PLACARD, S CLIPPER WORKHEAD TORQUES	473354
2	REF	PLACARD, S CLIPPER WORKHEAD TORQUES	473356
3	REF	SCR, DRIVE: #4 X .25	491673

INSTRUCTIONS:

- 1. LOCATE PLACARDS AS SHOWN, WITH A #37 (.104) DRILL BIT, TRANSFER HOLES THROUGH PLACARDS 3/8" DEEP AND INSTALL DRIVE SCREWS.
- 2. REPEAT ON OPPOSITE WORKHEAD.





REV	EN	DESCRIPTION					DATE	DRN				
1	3082	NEW R	ELEASE	-				4-18	MSO			
DIMENSION TOLERANCES UNLESS OTHERWISE SPECIFI												
LINEAR .XX=±.03						$\times = \pm$.	.010					
AN	GULAR	: X	X°=±1°			X.X°=±.5°						
SURFACE FINISH 125/ SMOOTH ALL SHARP EDGES NOT TO EXCEED CLEAN ALL WELDS												
THIS PRINT AND ALL INFORMATION WITHIN BELONGS TO RACINE RAILROAD PRODUCTS												
R		NE R Cine				_		DUCT	5			
DESCRIPTION												
INSTRUCTIONS, FASTENER TORQUE PLACARDS (NC)												
MATERIAL												
			SE	ΞE	BOI	4						
USED ON							E DA 0	TE 4-19-	18			
	CH	НK	APP		JOB	NO		SHEET				
MS	0				RD	140	001	1 OF	1			
EXP NO						DWG NO						
							8(0027	7			